## ABSTRACT OF THE DESCLOSURE

A method used to measure pressure in an area which is closed by an solenoid valve (106) performs the following steps: applying voltage to the solenoid valve (106), determining the peak of a curve of the flowing current based on voltage and determining the pressure based on determination of the peak of the curve.